

FIG. 1




FIG. 2




FIG. 3





FIG. 5

FIG. 6




FIG. 7




FIG. 8A




FIG. 8B




FIG. 8C




FIG. 8D




FIG. 8E




FIG. 8F




FIG. 9A




FIG. 9B




FIG. 9C




FIG. 9D




FIG. 9E




FIG. 10




FIG. 11




FIG. 11



FIG. 12A**FIG. 12B**

FIG. 13




FIG. 14




FIG. 14

FIG. 15

URL

TROUBLE DB INPUT WINDOW

OCCURRENCE DATE ~ 4040

TYPE OF APPARATUS ~ 4010

SUBJECT ~ 4030

SERIAL NUMBER S/N ~ 4020

DEGREE OF URGENCY ~ 4050

SYMPTOM ~ 4060

REMEDY ~ 4070

PROGRESS ~ 4080

4100 4110 4120

[LINK TO RESULT LIST DATABASE](#) [SOFTWARE LIBRARY](#) [OPERATING GUIDE](#)

FIG. 16





FIG. 17



00010670 029001